



Summary of Airworthiness Directives

published by Luftfahrt-Bundesamt / Germany

Luftfahrt-Bundesamt
Airworthiness Directive Section
38144 Braunschweig
G E R M A N Y

Tel. +49 (0) 531-2355-5223 email ad@lba.de
Fax +49 (0) 531-2355-5298 URL www.lba.de

Aircraft: Airbus Helicopters Deutschland GmbH / MBB-BK117

German Type Certificate No.: 3049 / EASA.R.010

No.	LTA-Nr.	Date of issue	Effected Series	Description of Problem	Service Bulletins (SB)	Note
1	1984-177/2	14.01.1985	all	Cargo hook - inadvertently release	BK 117 SB No. 80-4 Rev.1 dated 27.11.1984 Siren SB No. 10A dated 13.08.1984	supersedes AD 1984-177
2	1984-206	07.12.1984	A-1	Static longitudinal control travel stability	BK 117 SB No. 40-4 dated 19.11.1984	-
3	1985-050	18.02.1985	A-1	Control rods - Incorrect labelling of control rods	BK 117 AB No. BK 117-1	-
4	1985-208	09.10.1985	all	Main transmission gear / Correct installation of freewheel	BK 117 AB No. BK 117-2 dated 15.07.1985	-
5	1986-001/2	16.06.1987	all	Flight Control System - Installation of "Stick Position Augumentation System"	-	supersedes AD 1986-001
6	1986-022/2	14.10.1986	A-3	Tail rotor blades - Bonding due to improper possible separation of erosion protective shell	BK 117 AB No. BK 117-3 Rev. 1 dated 12.06.1986	supersedes AD 1986-022
7	1986-149	25.07.1986	all	Tail rotor gearbox - Attachment bolts P/N LN 9037-10040	BK 117 AB No. BK 117-4 dated 27.03.1986	-
8	1986-189	29.09.1986	A-1	Accessory Replacement Record - List of Time Change Items (TCI), Introduction of retirement time limits	BK 117 ASB No. BK 117-10-100 dated 07.07.1986	-
9	1986-190	29.09.1986	all	Check Tee Valve 35200100 - Possibility of a manufacturing defect	BK 117 ASB No. BK 117-70-100 dated 11.08.1986	-
10	1987-106/2	29.06.1987	all	Main rotor head - Hex. bolts for blade connections	BK 117 ASB No. BK 117-10-101 Rev. 1 dated 08.05.1987 and Rev. 2 dated 26.05.1987	supersedes AD 1987-106
11	1987-147	31.07.1987	A-1, A-3 and A-4	Flight Manual - Procedure modification in case of chip indication in engine oil system	BK 117 A-1 and A-3 Flight Manual Rev. 5 and A-4 Rev. 1 dated 27.07.1987	-
12	1988-122	12.07.1988	A-1, A-3 and A-4	General Lettering - Replacement of V _{NE} Schedule placard (Correction)	BK 117 ASB No. BK 117-70-101 dated 11.04.1988	-

13	1990-212/2	09.08.1990	all	Electrical bonding / Electrostatics / Fuel System - Reduction of fire hazard	BK 117 ASB No. BK 117-90-104, -90-105, -60-107 and SB No. BK 117-60-108	supersedes AD 1990-212
14	1994-280R5	29.09.2009	BK117A-1, A-3, A-4, B-1, B-2 and C-1	Main Rotor – Main Rotor (MR) Blades – Inspection / Replacement	Eurocopter Deutschland ASB-MBB-BK 117-10-108, Rev. 4, dated 17.08.2009	supersedes AD 1994-280R4
15	1995-242	13.06.1995	A-1, A-3, A-4, B-1, B-2 and C-1	Life limited parts - changing life limitations and introducing new life limited parts	BK 117 ASB No. BK 117-10-106 Rev. 1 dated 07.11.1994, No. BK 117-10-109 and -110 both dated 01.12.1994	-
16	1997-144R4	30.11.2005	A-1, A-3, A-4, B-1, B-2 and C-1	Failure of the vertical fin of the tail boom	Eurocopter Deutschland ASB-MBB-BK 117-30-106, Rev. 5, dated 04.10.2005	supersedes AD 1997-144/3
17	1997-276R1	04.10.2017	MBB-BK117 A-1, A-3, A-4, B-1, B-2 und C-1	(ATA 63) Rotor Drive – Main Rotor Mast - Inspection	ECD ASB-MBB-BK 117-10-114, dated 27.08.1997 or AH ASB MBB-BK117-10-114 Rev. 1, dated 28.07.2017	supersedes AD 1997-276
18	1997-350	18.12.1997	all	Main gear / main transmission - Life limited parts -	BK 117 ASB No. BK 117-10-113 dated September 30, 1997	-
19	1999-284R4	22.07.2013	MBB-BK117 A-1, MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, MBB-BK 117 B-2, MBB-BK 117C-1	(ATA 04) Time Limits and Maintenance Checks – Airworthiness Limitation Items – Amendment	MBB-BK117 A-1 bis B-2 Aircraft Maintenance Manual Appendix A15 with Rev. 42a MBB-BK117 C-1 Aircraft Maintenance Manual Appendix A15 with Rev. 25a	supersedes AD 1999-284R3
20	1999-302	23.09.1999	all	Fuselage - Retrofit of a hook system for the doors of the transmission and engine cowlings	BK 117 SB No. BK-117-20-109, Rev. 2 dated 30.04.1999	-
21	2003-161	29.04.2003	A-1 up to C-1	Tail Rotor Drive – Replacement of bearings in tail rotor transmission and intermediate gearbox, reduction of the inspection interval for magnetic plug	Eurocopter Deutschland MBB-BK 117 ASB No. ASB-MBB-BK 117-30-108, dated 14.04.2003	-
22	2003-219	21.08.2003	A-1 up to B-2 and C-1	Tail unit – Inspection of the Wall Thickness of the Skin Panelling of the Vertical Fin	Eurocopter Deutschland MBB-BK117 ASB No. ASB-MBB-BK117-30-109 Rev. 1, dated 03.07.2003	-
23	2005-115	15.03.2005	A-1 up to C-1	Main Rotor System – Introduction of a life limit for main rotor blades with bolted lead inner weights	Eurocopter Deutschland MBB-BK117 ASB No. ASB-MBB-BK117-10-125, dated 14.02.2005	-

24	2006-370R2	16.04.2008	MBB BK 117 C-1 and C-2	Placards & Markings – Pressure Altitude (PA) – Limitation Rotorcraft Flight Manual – Amendment Power Plant – Engine 'MAX N1' – Check	Eurocopter Deutschland ASB-MBB-BK117-60-121 Rev. 4, dated 11.12.2007 Eurocopter Deutschland ASB MBB BK117 C-2-71A-003 Rev. 3, dated 11.12.2007	supersedes AD 2006-370R1
25	2007-207	06.06.2007	MBB-BK 117 C-2	Fire Protection System – Fire Extinguishing System Injection Tube Clamps - Replacement	Eurocopter Deutschland ASB MBB BK 117 C-2-26A001, dated 22.01.2007	-
26	2007-247R1	03.12.2007	MBB-BK 117 C-2	Tail Rotor System – Control Lever – Inspection/Replacement	Eurocopter Deutschland ASB MBB BK 117 C-2-64A-002 Rev. 1, dated 09.07.2007 Eurocopter Deutschland ASB MBB BK 117 C-2-64A-002 Revision 2 , dated 06.08.2007	supersedes AD 2007-247R1
27	2008-243	10.07.2008	EC135 series, EC635 series and MBB-BK 117 C-2	Rotors Flight Control – Cyclic-Stick Locking Device – Modification	Eurocopter Deutschland ASB EC135-67A-015, dated 14.04.2008 Eurocopter Deutschland ASB MBB BK117C-2-67A-008, dated 14.04.2008	-
28	2008-388	11.12.2008	BO 105 A, BO 105 C, BO 105 LS A-1, BO 105 D, BO 105 DS, BO 105 DB, BO 105 DBS, BO 105 DB-4, BO 105 DBS-4, BO 105 DBS-5, BO 105 S, MBB-BK 117 A-1, MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, MBB-BK 117 B-2, MBB-BK 117 C-1	Tail Rotor – Balance Weights & Control Lever- Inspection / Replacement	Eurocopter Deutschland GmbH BK 117 ASB-MBB-BK117-30-113, dated 23.09.2008 Eurocopter Deutschland GmbH BO105 ASB BO105-30-116, dated 23.09.2008	-
29	2009-072R2	19.09.2017	MBB-BK 117 C-2	(ATA 04) Time Limits / Maintenance Checks – Airworthiness Limitations – Revision	AHD MBB BK 117 C-2 MSM Rev. 17, dated 07.05.2015, or Rev. 18, dated 21.03.2016, or Rev.19, dated 31.10.2016, or Rev. 20, dated 02.05.2017 AHD ASB MBB-BK 117 C-2-04A-008, dated 27.04.2017	supersedes AD 2009-072R1

30	2009-092R1	08.09.2010	EC 135 P1(CDS), EC 135 P1(CPDS), EC 135 P2(CPDS), EC 135 P2+, EC 135 T1(CDS), EC 135 T1(CPDS), EC 135 T2(CPDS), EC 135 T2+, EC 635 T1(CPDS), EC 635 P2+, EC 635 T2+, MBB-BK 117 C-2	Optional Equipment – External Mounted Hoist System – Visual Check / Replacement	Eurocopter Deutschland ASB MBB BK117 C-2-85A-024 Rev. 1, dated 23.06.2010 ASB EC135-85A-036 Rev. 2, dated 23.06.2010 Goodrich Corporation SB 44307-500-03 Rev. 2, dated 30.04.2010	supersedes AD 2009-092
31	2009-110R1	25.03.2010	BO 105 A, BO 105 C, BO 105 D, BO 105 LS A-1, BO 105 LS A-3, BO 105 S, MBB-BK 117 A-1, MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, MBB-BK 117 B-2, MBB-BK 117 C-1	Rotors Flight Control – Cyclic-Stick Locking Device – Modification	Eurocopter Canada Limited ASB-BO 105 LS 40-10, dated 08.05.2009 Eurocopter Deutschland ASB BO105-40-106, dated 19.12.2008 ASB MBB-BK117-40-113, dated 22.12.2008	supersedes AD 2009-110
32	2009-159R2	07.06.2010	MBB-BK 117 C-2	Airworthiness Limitations – Tail Rotor Intermediate Gear Box (IGB) Bevel Gear - Reduced Life Limit	ECD ASB MBB BK117 C-2-04A-005, Rev. 02, dated 28.04.2010	supersedes AD 2009-159R1
33	2009-164	22.06.2009	MBB-BK 117 C-2	Tail Rotor Drive – Tail Rotor (T/R) Drive Shaft – Inspection	Eurocopter Deutschland ASB MBB BK 177 C-2-65A-003, dated 04.05.2009	-
34	2009-182R3	12.02.2010	Alle	Equipment / Furnishings – D-Lok Hook of the Rescue Hoist – Inspection / Removal from Service / Replacement	FAA Airworthiness Directive 2010-03-02 – Lifesaving Systems Corp.	supersedes AD 2009-182R2
35	2010-094R1	01.04.2010	MBB-BK 117 C-2	(ATA 67) Rotor Flight Controls – Upper Control Bellcrank Assembly – Modification / Inspection / Replacement	Eurocopter Deutschland GmbH ASB MBB BK117 C-2-67A-011 Rev. 1, dated 23.02.2010	supersedes AD 2010-094

36	2010-111R2	10.04.2017	EC 135 P1(CDS), EC 135 P1(CPDS), EC 135 P2(CPDS), EC 135 P2+, EC 135 T1(CDS), EC 135 T1(CPDS), EC 135 T2(CPDS), EC 135 T2+, EC 635 T1(CPDS), EC 635 P2+, 635 T2+, MBB-BK 117 C-2	Rotor Flight Controls - Tail Rotor, Cyclic and Collective Control Levers - Inspection / Repair	Eurocopter Deutschland GmbH ASB EC135-67A-019 Rev. 3, dated 16.12.2009 or Rev. 4, dated 03.04.2017 ASB MBB BK117 C-2-67A-010 Rev. 3, dated 08.02.2010	supersedes AD 2010-111R1
37	2010-215R3	28.06.2013	AB139 , AW139, S-92A, MBB-BK117 C-2, EC 135	(ATA 25) CANCELLED: Equipment / Furnishings - Spectrolab Nightsun XP Searchlight - Inspection / Removal / Replacement	Eurocopter UK Ltd. SB 1351151-472 Issue A, dated 10.11.2010 SB 1451167-473 Issue A, dated 10.11.2010 SB 135787-467 Issue A, dated 10.11.2010 Agusta B.T. 139-231, dated 18.11.2010 Keystone Helicopter SB 10-11 Rev. C, dated 22.10.2010	supersedes AD 2010-215R2
38	2010-283R1	08.11.2011	EC 135 P1 (CDS), EC 135 P1 (CPDS), EC 135 P2 (CPDS), EC 135 P2+, EC 135 T1 (CDS), EC 135 T1 (CPDS), EC 135 T2 (CPDS), EC 135 T2+, EC 635 T1 (CPDS), EC 635 P2+, EC 635 T2+, MBB-BK 117 C-2	(ATA 31) Indicating and Recording Systems - Instrument Control Panel - Flight Limitation / Modification	Eurocopter Deutschland ASB EC135-31A-053 Rev. 2, dated 23.05.2011 ASB MBB BK 117 C-2-31A-041, Rev. 2 dated 23.05.2011	supersedes AD 2010-283
39	2010-317R2	23.03.2018	EC135 P1 CPDS), EC135 P2 (CPDS), EC135 P2+, EC135 T1 (CPDS), EC135 T2 (CPDS), EC135 T2+, EC635 T1 (CPDS), EC635 P2+, EC635 T2+, MBB-BK117 C-2	(ATA 33) Lights - Instrument Lighting Display Brightness - Modification	Eurocopter Deutschland ASB EC135-33A-009 Rev. 2, dated 30.06.2011 ASB MBB-BK117 C-2-33A-013 Rev. 2, dated 30.06.2011 SB MBB-BK117 C-2-33-006, dated 04.10.2007 or Rev. 1, dated 15.09.2008 or Rev. 2, dated 12.04.2011 or Airbus Helicopters Deutschland SB MBB-BK117 C-2-33-006 Rev. 3, dated 24.04.2014	supersedes AD 2010-317R1

40	2010-340R1	10.10.2011	MBB-BK117 C-2	Electrical Power – Generator Relay After Junction Box- Modification	Eurocopter Deutschland ASB MBB-BK117 C-2-24A-008, Rev. 1, dated 29.08.2011 Eurocopter Deutschland MBB-BK117 C-2 Rotorcraft Flight Manual TR 11, dated 09.08.2011	supersedes AD-2010-340
41	2010-341	22.12.2010	MBB-BK 117 C-2	Auto Flight – Three-Axis-Autopilot Automatic Level-off Function – Revised Flight Manual Procedure	Eurocopter Deutschland ASB MBB BK117 C-2-22A-012, dated 20.12.2010	-
42	2011-043	23.03.2011	MBB-BK 117 C-2	Rotor Flight Controls – Main Rotor Controls Power Boosted Section – Inspection / Rigging	Eurocopter Deutschland (ECD) ASB MBB BK117 C-2-67A-012, dated 16.09.2010 MBB BK117 C-2 AMM, TR 12b, dated 16.09.2010	-
43	2011-120R2	30.07.2012	MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, MBB-BK 117 B-2, MBB-BK 117 C-1	(ATA 85) Optional Equipment – External Rescue Hoist System – Deactivation / Modification	Eurocopter Deutschland EASB MBB BK117-80-166, Rev. 1, dated 04.08.2011	supersedes AD 2011-120R1
44	2011-143R1	04.10.2011	MBB-BK 117 C-2	(ATA 24) Electrical Power – Generator Control Unit – Identification / Replacement	Eurocopter Deutschland (ECD) ASB MBB BK117 C-2-24A-008, Rev. 1, dated 29.08.2011 ASB MBB BK117 C-2-24A010, Rev. 1, dated 01.07.2011 ASB MBB BK117 C-2-24A-010, Rev. 2, dated 14.09.2011	supersedes AD 2011-143
45	2011-186	02.11.2011	MBB-BK 117 C-2	(ATA 24) Electrical Power – Generator Control Unit – Identification / Replacement	Eurocopter Deutschland ASB MBB BK117 C-2-24A-006, Rev. 3, dated 06.07.2011	-
46	2011-204	12.12.2011	MBB-BK117 A-1, MBB-BK117 A-3, MBB-BK117 A-4, MBB-BK117 B-1, MBB-BK117 B-2, MBB-BK117 C-1	(ATA 24) Electrical Power – Generator Control Unit – Identification / Replacement	Eurocopter Deutschland ASB MBB-BK117-90-122, dated 10.10.2011	-
47	2011-221	30.12.2011	MBB-BK 117 C2	(ATA 52) Doors – Sliding Door Emergency Jettison System – Inspection	Eurocopter Deutschland (ECD) ASB MBB BK117 C-2-52A-015, dated 26.04.2011	-

48	2012-308	01.08.2012	MBB-BK117 A-1, A-3, A-4,B-1, B-2, C-1 and C-2, BO 105 LS A-3, BO 105 LS A-3 "Superlifter" (LBA EMZ 0654/3058 und EASA STC 10039633)	(ATA 64) Tail Rotor Pitch Links (Improperly Repaired by Able Engineering & Component Services) – Inspection	Able Engineering & Component Services ASB No. 2012-001, Rev. IR, dated 07.03.2012	-
49	2012-393	19.10.2012	MBB-BK117 C-2	(ATA 22) Auto Flight – Autopilot – Dispatch Restriction	Eurocopter Deutschland GmbH ASB MBB-BK117 C-2-22A-013, dated 12.10.2012 Master Minimum Equipment List BK117 C-2 (EC145) Series dated 12.03.2012	-
50	2012-466R1	23.08.2013	MBB-BK 117 C-2	(ATA 33) Lighting - Flight Control Display System Wire Harness - Modification	Eurocopter Deutschland EASB MBB-BK117 C-2-88A-008, dated 17.12.2012 EASB MBB-BK117 C-2-88A-008, Rev. 01, dated 01.07.2013	supersedes AD 2012-466
51	2013-079R13	13.08.2020	AW109SP, AB139, AW139 and AB412 (all Models). BHTI Bell 212, 214 and 412 (all Models). BHTC Bell 429 and 430. AH AS 365 N3, AS 332 L2 and EC225 LP. AHD MBB-BK117 C-2, EC135 and EC635 (all Models). MDHI MD900. Sikorsky S-61 (all Models), S-76A, S76B, S-76C and S-92A.	(ATA 25) Equipment / Furnishing - Hoist - Test / Replacement	AHD ASB MBB-BK117 C-2-85A-038, Rev. 5, dated 18.11.2015 or Rev. 6, dated 17.03.2016 ASB MBB-BK117 C-2-85A-045, dated 18.11.2015 ASB EC135-85A-058, Rev. 6, dated 19.11.2015 or Rev. 7, dated 17.03.2016 or Rev. 8, dated 17.05.2016 ASB EC135-85A-064, dated 19.11.2015 AH ASB AS365-25.01.25, Rev. 6, dated 19.11.2015 or Rev. 7, dated 17.03.2016 ASB AS365-25.01.65, dated 19.11.2015 or Rev. 1, dated 24.05.2016 ASB AS332-25.02.70, Rev. 6, dated 19.11.2015 or Rev. 7, dated 17.03.2016 ASB AS332-25.03.19, dated 19.11.2015 or Rev. 1 dated 24.05.2016 ASB EC225-25A133, Rev. 6, dated 19.11.2015 or Rev. 7, dated 17.03.2016 ASB EC225-25A187, dated 19.11.2015 or Rev. 1, dated 24.05.2016 Leonardo, Helicopter Division: BT139-443, dated 19.11.2015 or Rev. A, dated 21.04.2016 BT 109SP-100, dated 19.09.2015 or Rev. A, dated 21.04.2016 BHTC ASB 429-14-15, Rev. B, dated 10.03.2016 (see Note 4 of this AD)	supersedes AD 2013-079R12

52	2013-209	05.08.2013	MBB-BK 117 A-1, A-3, A-4, B-1, B-2, C-1 and C-2	(ATA76) Engine Controls - N2 Control Arm - Inspection / Modification	Eurocopter Deutschland ASB MBB-BK117 C-2-76A-005, dated 24.06.2013 ASB MBB-BK117-60A-126, dated 24.06.2013	-
53	2013-216R2	31.07.2014	MBB-BK 117 A-3, A-4, B-1 and C-2	(ATA 65) Air Conditioning Drive Pulley - Inspection	Metro ASB MA145-21B-003 Rev. B, dated 20.12.2013	supersedes AD 2013-216R1
54	2013-220	14.08.2013	EC 135 P1 (CDS), EC 135 P1 (CPDS), EC 135 P2+, EC 135 P2 (CPDS), EC 135 T1 (CDS), EC 135 T1 (CPDS), EC 135 T2+, EC 135 T2 (CPDS), EC 635 P2+, EC 635 T1 (CPDS), EC 635 T2, MBB-BK 117 C-2	(ATA 22) Auto Flight System - Longitudinal, Lateral and Yaw Actuator / Control Rod Attachment Hardware - Inspection / Replacement	Eurocopter Deutschland ASB EC135-22A-015, dated 13.05.2008 ASB EC 135-22A-015, Rev. 01, dated 28.01.2013 ASB MBB BK117 C-2-22A-009, dated 13.05.2008 ASB MBB BK117 C-2-22A-009, Rev. 01, dated 03.08.2009 EC 135 AMM Rev. 10 or later MBB BK 117 C-2 AMM Rev. 12 or later	-
55	2013-232	26.08.2013	MBB-BK 117 C-2	(ATA 67) Rotor Flight Controls - Lateral and Longitudinal Trim Actuator - Inspection	Eurocopter Deutschland ASB MBB-BK117 C-2-67A-20, dated 18.06.2013	-
56	2014-064R3	25.02.2015	MBB-BK117 C-2, MBB-BK117 D-2	(ATA 85) Optional Equipment - External Rescue Hoist System - Inspection / Modification	AHD ASB MBB-BK117 C-2-85A-041 Rev. 3, dated 03.02.2015 or Rev. 4, dated 12.02.2015 ASB MBB-BK117 D-2-85A-002, dated 03.02.2015 or Rev. 1, dated 12.02.2015	supersedes AD 2014-064R2
57	2014-148	22.05.2014	MBB-BK117 C-2	(ATA 22) Auto Flight - Automatic Flight Control System Wiring - Modification Rotorcraft Flight Manual - Amendment	AHD SIN 2659-S-22 Rev. 0, dated 15.01.2014 AHD SB MBB-BK117 C-2-22-016 Rev. 0, dated 08.04.2014 AHD BK117 C-2 AFCS FMS 9.2-1 Temp. Rev. 13	-

58	2014-204R5	13.04.2018	<p>MBB-BK117 A-1, MBB-BK117 A-3, MBB-BK117 A-4, MBB-BK117 B-1, MBB-BK117 B-2, MBB-BK117 C-1, MBB-BK117 C-2, MBB-BK117 C-2e, BO105 A, BO105 C, BO105 D, BO105 S, BO105 LS A-3</p>	(ATA 62) Main Rotor - Swashplate Assembly – Replacement / Inspection	<p>AHD ASB MBB-BK117-40A-115, dated 31.03.2014 or Revision 1, dated 04.08.2014 or Revision 2, dated 30.07.2015, or Revision 3, dated 08.02.2016, or Revision 4, dated 23.05.2016, or AH ASB MBB-BK117-40A-115 Revision 5, dated 25.07.2017 (including Correction dated 02.02.2018) AHD ASB MBB-BK117C-2-62A-007, dated 31.03.2014 or Revision 1, dated 04.08.2014 or Revision 2, dated 30.07.2015 or Revision 3, dated 08.02.2016, or Revision 4, dated 23.05.2016, or AH ASB MBB-BK117 C-2-62A-007, Revision 5, dated 25.07.2017 (including Correction dated 02.02.2018) AHD ASB BO105-40A-107, dated 31.03.2014 or Revision 1, dated 08.09.2014 or Revision 2, dated 30.07.2015 or Revision 3, dated 08.02.2016, or Revision 4, dated 23.05.2016, or AH ASB BO105-40A-107 Revision 5, dated 25.07.2017 (including Correction dated 02.02.2018) AHD ASB BO105LS-40A-12, dated 31.03.2014 or Revision 1, dated 08.09.2014 or Revision 2, dated 30.07.2015 or Revision 3, dated 08.02.2016, or Revision 4, dated 23.05.2016, or AH ASB BO105LS-40A-12 Revision 5, dated 25.07.2017 (including Correction dated 02.02.2018) AHD ASB BO105 LS A-3-STC-0654/3058-40A-2, dated 08.02.2016, or Revision 1, dated 23.05.2016, or AH ASB BO105 LS A-3-STC-0654/3058-40A-2 Revision 2, dated 25.07.2017 (including Correction dated 02.02.2018)</p>	supersedes AD 2014-204R4
----	------------	------------	--	--	---	--------------------------

59	2014-228R2	31.03.2015	SA 365 N, SA 365 N1, AS 365 N2, AS 365 N3, EC 155 B, EC 155 B1, AS 332 C, AS 332 C1, AS 332 L, AS 332 L1, AS 332 L2, EC 225 LP, MBB-BK 117 A-1, MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, MBB-BK 117 B-2, MBB-BK 117 C-1, MBB-BK 117 C-2, AB 212, AB 412, AB 412EP	(ATA 25) Equipment & Furnishings - Emergency Flotation System - Rotorcraft Flight Manual (Supplement)	-	supersedes AD 2014-228R1
60	2014-246	24.09.2014	MBB-BK117 C-2	(ATA 88) Wiring / Harness - Hoist Control Pendant Wiring Harness - Inspection / Modification	AHD ASB MBB-BK117 C-2-88A-009, dated 18.06.2014	-
61	2015-077	27.03.2015	MBB-BK117 C-2	(ATA 24) Electrical Power - Terminal Lugs - Inspection / Replacement	AHD ASB MBB-BK117 C-2-24A-013 Rev. 0, dated 29.10.2014 or Rev. 1, dated 25.11.2014	-
62	2015-078R2	07.04.2015	MBB-BK117 C-2, MBB-BK117 C-2e, MBB-BK117 D-2, MBB-BK117 D-2m	(ATA 62) Main Rotor - Main Rotor Blade Vibration Absorber - Modification	AHD ASB MBB-BK117 C-2-62A-009, dated 20.01.2015 or Revision 1, dated 28.10.2015 AHD ASB MBB-BK117 D-2-62A-001, dated 20.01.2015 or Revision 1, dated 28.10.2015	supersedes AD 2015-078R1
63	2015-128	09.06.2015	MBB-BK117 A-1, MBB-BK117 A-3, MBB-BK117 A-4, MBB-BK117 B-1, MBB-BK117 B-2, MBB-BK117 C-1	(ATA 90) Electrical Power - Ground Reference Connection - Retrofit / Rotorcraft Flight Manual - Amendment	BK117 A-3 RFM, TR 9, dated 22.09.2006 BK117 A-4 RFM, TR 5, dated 22.09.2006 BK117 B-1 RFM, TR 6, dated 22.09.2006 BK117 B-2 RFM, TR 1, dated 22.09.2006 BK117 C-1C RFM, TR 1, dated 22.09.2006 BK117 C-1 RFM, TR 2. Dated 22.09.2006 ECD ASB-MBB-BK117-90-118 Revision 02, dated 04.05.2009	-
64	2015-177	30.07.2015	MBB-BK117 C-2	(ATA 88) Wiring / Harness - Collective Lever Wiring Harness - Inspection	AHD ASB MBB-BK117 C-2-88A-010 Revision 1, dated 16.04.2015	-
65	2015-191R1	02.05.2016	MBB-BK117 A-3 MBB-BK117 A-4 MBB-BK117 B-1 MBB-BK117 B-2 MBB-BK117 C-1	(ATA 52) Doors - Jettison System Adhesive Seal - Removal	AHD ASB MBB-BK117-20A-114 Revision 1, dated 30.07.2015, or Revision 2 dated 30.03.2016	supersedes AD 2015-191

66	2015-239R2	11.11.2019	MBB-BK117 D-2	(ATA 71) Power Plant - Engine Mount Bushings – Inspection / Replacement	AHD ASB MBB-BK117 D-2-71A-002, dated 28.09.2015 or AH ASB MBB-BK117 D-2-71A-002 Revision 01, dated 14.12.2018 AH ASB MBB-BK117 D-2-71A-011, dated 16.10.2019	supersedes AD 2015-239R1
67	2015-250R3	16.03.2017	MBB-BK117 C-2, MBB-BK117 C-2e, MBB-BK117 D-2, MBB-BK117 D-2m	(ATA 29) Hydraulic Power - Plate Assembly Attachment Points - Inspection / Check	AHD ASB MBB-BK117 C-2-29A-003, dated 12.10.2015, or Revision 1, dated 14.10.2016, or Revision 2, dated 01.02.2017 AHD ASB MBB-BK117 D-2-29A-001, dated 12.10.2015, or Revision 1, dated 14.10.2016, or Revision 2, dated 01.02.2017	supersedes AD 2015-0250R2
68	2016-002	06.01.2016	MBB-BK117 C-2, MBB-BK117 C-2e, MBB-BK117 D-2, MBB-BK117 D-2m	(ATA 21) Air Conditioning - Air Inlet Cover Ring - Inspection / Modification	AHD ASB MBB-BK117 C-2-21A-011, dated 16.11.2015 AHD ASB MBB-BK117 D-2-21A-004, dated 16.11.2015	-
69	2016-190	14.07.2016	MBB-BK 117 A-1, MBB-BK 117 A-3, MBB-BK 117 A-4, MBB-BK 117 B-1, MBB-BK 117 B-2, MBB-BK 117 C-1, MBB-BK 117 C-2, MBB-BK 117 C-2e	(ATA 65) Tail Rotor Drive - Tail Rotor Gearbox Housing - Inspection	AHD ASB MBB-BK117-30A-119, dated 24.05.2016 AHD ASB MBB-BK117 C2-65A-007, dated 24.05.2016	-
70	2017-042	23.02.2017	MBB-BK117 D-2 MBB-BK117 D-2m	(ATA 63) Main Rotor Drive - Rotor Mast Nut and Helical Gear Support - Re-identification	AH ASB MBB-BK117 D-2-63A-001, dated 01.12.2016	-
71	2017-043	23.02.2017	MBB-BK117 D-2 MBB-BK117 D-2m	(ATA 67) Rotors Flight Control - Cable Cut Flip Guard - Replacement	AH ASB MBB-BK117 D-2-67A-002, dated 23.01.2017	-
72	2017-045	24.02.2017	MBB-BK117 C-2 MBB-BK117 C-2e MBB-BK117 D-2 MBB-BK117 D-2m	(ATA 24) Electrical Power - Overhead Panel Shock Mounts - Replacement	AH ASB MBB-BK117 C-2-24A-015, dated 14.09.2016 AH ASB MBB-BK117 D-2-24A-004, dated 14.09.2016	-
73	2017-121	01.06.2017	MBB-BK117 D-2	(ATA 67) Rotors Flight Control - Trim Actuators - Replacement	AH ASB MBB-BK117 D-2-67A-005, dated 03.04.2017	-

74	2017-189R2	23.08.2019	MBB-BK117 D-2	(ATA 42) Integrated Modular Avionics – Aircraft Management Computer Software - Update	AH Flight Manual BK117 D-2, TR No. 2, dated 20.11.2017 Flight Manual BK117 D-2 (Helionix Step 2), TR No. 2, dated 20.11.2017 Flight Manual BK117 D-2m (Helionix Step 2), TR No. 2, dated 20.11.2017 ASB MBB-BK117 D-2-42A-004, dated 04.09.2018 ASB MBB-BK117 D-2-42A-005, Rev. 3, dated 06.06.2019	supersedes AD 2017-189R1
75	2017-221	22.09.2017	MBB-BK117 C-2 MBB-BK117 D-2	(ATA 25) Equipment & Furnishing - Outboard Load System - Inspection / Replacement	AH ASB MBB-BK117 C-2-85A-042, dated 24.07.2017 AH ASB MBB-BK117 D-2-85A-003, dated 24.07.2017	-
76	2017-284	04.12.2017	MBB-BK117 D-2	(ATA) Rotorcraft Flight Manual – Emergency Procedures Section – Amendment	AH Flight Manual BK117 D-2, TR 2, dated 20.11.2017 AH Flight Manual BK117 D-2 (Helionix Step 2), TR2, dated 20.11.2017 AH Flight Manual BK117 D-2m (Helionix Step 2), TR 2, dated 20.11.2017	-
77	2018-053	22.02.2018	MBB-BK117 A-1, MBB-BK117 A-3, MBB-BK117 A-4, MBB-BK117 B-1, MBB-BK117 B-2, MBB-BK117 C-1, MBB-BK117 C-2	(ATA 65) Tail Rotor Drive – Tail Gear Box – Inspection / Replacement	AH ASB MBB-BK117-30A-120, dated 31.01.2018 AH ASB MBB-BK117 C-2-65A-008, dated 31.01.2018	-
78	2018-077	22.03.2018	MBB-BK117 A-1, MBB-BK117 A-3, MBB-BK117 A-4, MBB-BK117 B-1, MBB-BK117 B-2, MBB-BK117 C-1	(ATA 62) Main Rotor – Blades Thimble – Inspection	AH ASB MBB-BK117-10A-137, dated 19.02.2018	-
79	2018-195	03.08.2018	MBB-BK117 D-2	(ATA 67) Rotorcraft Flight Controls – Co-pilot Collective Lever Wire Harness – Inspection	AH ASB MBB-BK117 D-2-67A-007, dated 23.07.2018	-

80	2018-262	18.10.2018	MBB-BK117 C-2 MBB-BK117 D-2	(ATA 25) Equipment & Furnishing – Hook Mount Assembly – Inspection	AH ASB MBB-BK117 C2-85A-047 deated 15.10.2018 AH ASB MBB-BK117 D-2-85A-022 dated 15.10.2018	-
81	2018-333R1	19.11.2020	MBB-BK117 C-2 MBB-BK117 D-2	(ATA 67) Rotors Flight Control - Main Rotor Actuator - Inspection	AH ASB MBB-BK117 C-2-67A-028, dated 07.07.2020 ASB MBB-BK117 D-2-67A-015, dated 07.07.2020	supersedes AD 2020-0257
82	2019-208	21.08.2019	MBB-BK117 D-2	(ATA 27) Flight Controls - Wiring Harness - Modification	AH ASB MBB-BK117 D-2-88A-002, dated 04.06.2019	-
83	2019-236	17.09.2019	MBB-BK117 C-2	(ATA 53) Fuselage - Fuselage Frame - Inspection	Air Methods ASB19-03 Rev. IR, dated 06.05.2019	-
84	2019-272	25.10.2019	MBB-BK117 D-2	(ATA 65) Tail Rotor Drive - Titanium Bolts - Inspection / Replacement	AHD ASB MBB-BK117 D-2-00A-001 Rev. 1, dated 16.10.2019	-
85	2019-324	18.12.2019	MBB-BK117 D-2	(ATA 88) Wiring Harness - Cabin Wiring Harness - Inspection	AH ASB MBB-BK117 D-2-88A-003, dated 26.11.2019 or Rev. 01, dated 09.12.2019	-
86	2019-328	20.12.2019	MBB-BK117 C-2	(ATA 67) Rotors Flight Control - Tail Rotor Actuator - Inspection	AH MBB-BK117 C-2-67A-027, dated 09.12.2019 or Rev. 1, dated 17.12.2019	-
87	2020-037	10.02.2020	AS 332 C, C1, L, L1 und L2, AS 365 N2 und N3, EC 155 B und B1, EC 175 B, EC 225 LP, SA 330 J, SA 365 C1, C2, C3, N und N1. EC135 P1, P2, P2+, P3, T1, T2, T2+ und T3, EC635 P2+, P3, T1, T2+ und T3, MBB-BK117 A-1, A-3, A-4, B-1, B-2, C-1, C-2 und D-2. AB139, AB 204 B, AB 205 A-1, AB 212, AB 412, AB 412 EP, AS-61N, AS-61N1, AW139, AW169 und AW189. PZL W-3A und PZL W-3AS	(ATA 26) Fire Protection - Hand-held Fire Extinguishers - Replacement	umlaut engineering GmbH VSB P3VSB000001 Issue C, dated 13.12.2019	-

88	2020-083	24.03.2020	MBB-BK117, EC 135, EC 120, EC 175, AS 332, AS 350, EC 130, AS 355, SA 365, AS 365 und EC 155	(ATA 25) Equipment / Furnishings - Emergency Flotation System / Inflation Hoses - Inspection	AHD ASB MBB-BK117 C-2-32A-011 Rev.1, dated 12.02.2020, AHD ASB MBB-BK117 D-2-32A-012 Rev.1, dated 12.02.2020, AHD ASB EC135-32A-028 Rev.1, dated 12.02.2020, AHD ASB EC135H-32A-005 Rev.1, dated 12.02.2020, AH ASB EC120-25A030 Rev.1, dated 12.02.2020, AH ASB EC175-25A041 Rev.1, dated 12.02.2020, AH ASB AS332-25.03.77, dated 07.01.2020, AH ASB AS350-25.04.10 Rev.1, dated 12.02.2020, AH ASB EC130-25A148 Rev.1, dated 12.02.2020, AH ASB AS355 25.01.30 Rev.1, dated 12.02.2020, AH ASB AS365-25.01.84, dated 07.01.2020, AH ASB AS365-25.01.85 Rev.1, dated 12.02.2020	-
89	2020-102	03.04.2020	MBB-BK117	(ATA 67) Rotors Flight Control - Collective Lever Switch Unit – Inspection	AH MBB-BK117 D-2-67A-013, dated 02.04.2020	-
90	2020-306	20.11.2020	MBB-BK117	(ATA 88) Wiring Harness – Lateral Control Rod Wiring – Inspection	AH ASB MBB-BK117 D-2-88A-006, dated 28.10.2020	-
				- END-		

Datum der letzten Änderung: 20.11.2020

Hinweis: Die Erstellung und Pflege der Übersichtslisten ist eine Service-Leistung des Luftfahrt-Bundesamtes. Obwohl wir die Übersichtslisten mit größtmöglicher Sorgfalt bearbeiten, können wir keine Fehler ausschließen. Bitte beachten Sie, dass deshalb keine Gewährleistung hinsichtlich Richtigkeit und Vollständigkeit für diese Listen übernommen werden kann. Weiterhin ist zu beachten, dass noch weitere Lufttüchtigkeitsanweisungen, z. B. für Motor, Propeller oder andere Ausrüstung für Ihr Luftfahrzeug gelten könnten.